

**OFFICE: Sub-Division Engineer ,
Provl. Sub Division , PWD B& R Nakodar, Punjab**

BUILDING SAFETY CERTIFICATE

File No: **58**

Dated: **15-7-26**


Certified that the existing building **Akal Academy Bilga** at **Village Bilga and Post Office: Bilga Tehsil: Phillaur, District Jalandhar** and **State: Punjab, Pin Code: 144036** is having Block(s)/ Floor(s) as per details below:

Detail of Block(s) in School	Block (1)	-
No. of Floor(s) in the Block	G+2	-

The building owned/occupied by **The Kalgidhar Society, Baru Sahib (H.P.)** have complied with the Building Safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of **Sub- division Engineer Provl sub division , PWD B & R Nakodar** on **16-07-2026** (Date of Inspection) in the presence of **(Principal) Akal Academy Bilga** (Name and Addresses of the Manager / Secretary or his representative) and that the building/ premises is fit for occupancy up to Classes XII with effect from **01.04.2026 to 01.04.2027** for a period of **one year** in accordance with rule and subject to compliance of the specific conditions as appended.

1. The water should not be allowed to stand around the building and on the roofs.
2. If any part of the building is exposed to any kind of cracks, the area should be vacated immediately and repaired immediately.
3. That the material used in the construction of the building shall be the responsibility of the concerned school.
4. Apart from the attached map, if any additional construction is to be done by you, then its approval should be taken from the department.

Issued on **15-7-26** at **P.W.D. (B&R) Nakodar, Punjab.**


The Executive Engineer,
Sub- Division Engineer
Provl Sub Division, PWD B&R Nakodar
Sub Divisional Engineer
Provl. Sub Division
PWD B & R Nakodar

